


ARDATZ_®PERFOR_®

9 64310 1 HSS TCT norm NPT Form C 1:16 8 05245 1



1:16

APPLICATIONS / ANWENDUNGEN



$\emptyset$	$\geq \uparrow P$	$\emptyset$ mm	L	l	$\emptyset$ mm	$\emptyset$ mm	TCT norm	$\emptyset$	$\geq \uparrow P$	$\emptyset$ mm	L	l	$\emptyset$ mm	$\emptyset$ mm	TCT norm
NPT 1/16	27	6,15	56	16	6	4,9	•	NPT 1/2	14	17,9	80	35	18	14,5	•
NPT 1/8	27	8,4	70	21	8	6,2	•	NPT 3/4	14	23,3	90	35	22	18	•
NPT 1/4	18	11,1	70	28	11	9	•	NPT 1"	11,5	29	110	45	25	20	•
NPT 3/8	18	14,3	75	28	14	11	•								


ARDATZ_®PERFOR_®

9 64301 1 HSS EE Sim DiN 5156 NPT Form C XL 8 05247 1



1:16

APPLICATIONS / ANWENDUNGEN



$\emptyset$	$\geq \uparrow P$	$\emptyset$ mm	L	l	$\emptyset$ mm	$\emptyset$ mm	SIM DiN 5156	$\emptyset$	$\geq \uparrow P$	$\emptyset$ mm	L	l	$\emptyset$ mm	$\emptyset$ mm	SIM DiN 5156
NPT 1/16	27	6,15	90	16	6	4,9	•	NPT 1/2	14	17,9	140	35	18	14,5	•
NPT 1/8	27	8,4	90	21	8	6,2	•	NPT 3/4	14	23,3	140	35	22	18	•
NPT 1/4	18	11,1	100	28	11	9	•	NPT 1"	11,5	29	160	45	25	20	•
NPT 3/8	18	14,3	110	28	14	11	•	NPT 1 1/4	11,5	73,7	170	45	32	24	•